



महाराष्ट्र शासन
कार्यकारी अभियंता यांचे कार्यालय,
सार्वजनिक बांधकाम विभाग, अहिल्यानगर -414 001



दुरध्वनी क्र.0241-2325086/2325334

E-mail ID- ahmednagar.ec@mahapwd.gov.in

जा.क्र.: रेशा/ न.क्र.23/ 8609 /सन 2026

दिनांक :- 05/6/2026

प्रति,

प्राचार्य,
उर्जा गुरुकुल, केडगाव,
ता.जि.अहिल्यानगर

विषय : शाळेची इमारत सुस्थितीत असलेचे प्रमाणपत्र देणेबाबत.

संदर्भ : 1)आपले कडील विनंती अर्ज दिनांक 02/06/2026
2)उपविभागीय अभियंता, सा.बां.उपविभाग,अहिल्यानगर यांचे कडील पत्र जा.क्र.रेशा
/1287/सन 2026 दि.08/07/2026

उपरोक्त विषयांकित बाबत आपले उर्जा गुरुकुल, केडगाव, ता. जि. अहिल्यानगर या शाळेची इमारत सुस्थितीत असल्याबाबतचे C.B.S.E. बोर्डाच्या विहित नमुन्यातील प्रमाणपत्र मिळणेबाबत संदर्भ क्र.1 अन्वये आपण या कार्यालयास विनंती केली आहे.

त्या अनुषंगाने उपविभागीय अभियंता, सा.बां.उपविभाग, अहिल्यानगर यांनी सदरील इमारतीची प्रत्यक्ष पाहणी करून C.B.S.E. च्या बोर्डाच्या विहित नमुन्याइकतील प्रमाणपत्र प्रतिस्वाक्षरीसाठी संदर्भ 2 अन्वये सादर केले आहे, सादर केलेल्या सदर प्रमाणपत्रावर प्रतिस्वाक्षरी करून सोबत पाठविण्यात येत आहे.

सोबत:- प्रमाणपत्र

(लक्ष्मीकांत जाधव)
कार्यकारी अभियंता
सार्वजनिक बांधकाम विभाग
अहिल्यानगर

प्रत- उपविभागीय अभियंता, सा.बां.उपविभाग, अहिल्यानगर यांना माहितीसाठी.



10-15-1912

10-15-1912

10-15-1912

10-15-1912

10-15-1912

10-15-1912

10-15-1912

10-15-1912





BUILDING SAFETY CERTIFICATE

No.DB/BSC/ 4701 /2026

Date :- 09/07/2026

Certified that the existing building Urja Gurukul, Ahilyanagar (Name of the building or premises) at S.No.१०३, Kedgaon Devi Road, Kedgaon Tal. & Dist. Ahilyanagar is having block (S) as per details below:

Detail of Block (s) in School	Block(1)		
No.of Floor (s) in the block	03		


The building is owned/occupied by **Urja Gurukul S.No.103, Kedgaon Devi Road, Kedgaon Tah & Dist Ahilyanagar** (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules and verified by the concerned Architect/Structural Engineer (**Mr.Satish Shinde**), e o s structural consultant and agreed upon by officers concerned of **Sub-Divisional Engineer, Public Works Sub Division, Ahilyanagar**. (Name of Department / Govt.) on Date:- 01/07/2026 (Date of inspection) in the presence of **Mrs. Shraddha Rathod Principal, Urja Gurukul, Ahilyanagar** (Name and addresses of the Manager / Secretary or his representative) and that the building/premises are fit for occupancy for running school with effect from 01/07/2026 for a period of 1 (One) Years in accordance with rule and subject to compliance of the specific conditions as appended.

1. This certificate is given on the basis of document submitted by the school, Structural stability Certificate given by Mr. Satish Shinde structural Engineer, e o s structural Consultant and reported by the technical staff of this office.
2. This considers that execution was done by the institute strictly as per designs and relevant Code provisions.
3. If any differences in designs and relevant code procisions this certificate was automatically cancelled.

Issued on 09/07/2026 at Ahilyanagar by Executive Engineer, Public Works Division, Ahilyanagar.


Sub Divisional Officer,
P.W.Sub-Division,
Ahilyanagar.



"Countersigned"

Executive Engineer
Public Works subDivision,
Ahilyanagar